

June 2021

Summary

- Boston Scientific has determined that dual chamber INGENIO™ family¹ pacemakers or cardiac resynchronization therapy pacemakers (CRT-Ps) may initiate Safety Mode later in device life (i.e., prior to reaching the Explant battery indicator) when the device's battery exhibits high internal impedance. This latent battery condition puts a device at risk for system resets to occur due to temporary high-power consumption related to telemetry attempts and subsequent reversion to Safety Mode to maintain back-up pacing. Although therapy is still provided when a device is in Safety Mode, replacement is required.
 - Approximately 48,000 active dual chamber INGENIO family pacemakers and CRT-Ps built with the Extended Life (EL) battery are included within this advisory population (Appendix A).
 - No affected devices remain available for implant.
- Boston Scientific has received 65 reports of events associated with dual chamber INGENIO family EL pacemakers and CRT-Ps, in which devices transitioned to Safety Mode prior to reaching the Explant battery indicator during interrogation attempts by either a programmer or a LATITUDE™ communicator.
 - The most common clinical impact has been early device replacement.
 - Myopotential oversensing-associated pacing inhibition, as well as phrenic nerve stimulation have been reported in some patients prior to device replacement due to non-programmable Safety Mode pacing parameters.
 - No patient deaths have been reported.
 - It is estimated that one third or more of affected devices will experience Safety Mode prior to reaching Explant battery indicator.
- If a device enters Safety Mode, schedule replacement. In situations where non-programmable Safety Mode pacing parameters (Table 1) may not provide optimal support of a patient's cardiac condition (e.g., adequacy of underlying escape rhythm, the need for AV/VV pacing for cardiac synchrony, and/or the potential for pacing inhibition due to myopotential oversensing), consider early device replacement per the following guidelines:
 - For dual chamber EL pacemakers, replace with a longevity remaining of 4 years (or less).
 - For CRT-Ps, replace with a longevity remaining of 3 years (or less).

¹The INGENIO family of DR EL pacemaker includes: VITALIO™ DR EL, INGENIO™ DR EL, and ADVANTIO™ DR EL pacemakers and INLIVEN™, INTUA™, and INVIVE™ CRT-Ps.

Boston Scientific Advisory: High Battery Impedance May Initiate Safety Mode in INGENIO™ Family DR EL Pacemakers and CRT-Ps

Dear Physician or Healthcare Professional,

This letter provides important information about dual chamber INGENIO™ family Extended Life (EL) pacemakers and cardiac resynchronization therapy pacemakers (CRT-Ps) and applies to approximately 48,000 active devices. You are receiving this letter because our records indicate you may be following one or more patients implanted with an affected device (Appendix A). The battery impedance within these devices increases over time, based on implant duration and power usage. This latent battery condition puts the device at risk for system resets to occur during telemetry attempts and may cause the device to enter Safety Mode prior to reaching the Explant battery indicator. Boston Scientific discontinued manufacturing dual chamber INGENIO EL pacemakers and CRT-Ps in 2018; these devices are no longer eligible for implant. The INGENIO devices built with the Standard Life (SL) battery, as well as all contemporary Boston Scientific pacemakers and CRT-Ps, have different batteries and have not exhibited this latent battery condition.

Please distribute a copy of this letter to all other physicians and healthcare professionals within your organization who need to be aware of this potential device behavior.

Description

Boston Scientific has received reports associated with dual chamber INGENIO family pacemakers and CRT-Ps built with the EL battery (Appendix A), in which the devices transitioned to Safety Mode during interrogation attempts by either a programmer or a LATITUDE™ communicator. Investigation has shown that the EL battery impedance increases over time, based on implant duration and power usage. This increased battery impedance may cause a device to exhibit transient voltage decreases during periods of high-power consumption associated with telemetry communication via a programmer or a LATITUDE communicator. If the battery voltage drops below a minimum threshold during communication attempts, the device will temporarily halt telemetry, and a system reset will be performed. The battery voltage recovers and pacing function resumes within one (1) second; however, subsequent telemetry attempts may result in additional system resets due to the high battery impedance. If three (3) system resets occur within a 48-hour period, the device is designed to immediately enter Safety Mode to maintain back-up pacing with pre-defined, non-programmable settings (Table 1). There is no delay in resumption of pacing when the device enters Safety Mode. When a device is in Safety Mode, replacement is required.

Table 1. Safety Mode Non-Programmable Parameters

| | |
|-------------------------|--|
| Mode | VVI (for CRT-Ps: biventricular pacing) |
| Rate | 72.5 ppm |
| Sensitivity | Automatic Gain Control (AGC) 0.25 mV |
| Output | 5.0 V at 1.0 ms RV (and LV for CRT-Ps) |
| Lead Configuration | RV Unipolar sensing/pacing LV Unipolar (tip to can) |
| RVRP | 250 ms |
| Noise response | VOO |
| LV Offset (CRT-Ps only) | 0 ms |
| Magnet Response | Disabled |

Boston Scientific transvenous pulse generators contain dedicated hardware to support overall safety architecture. In pacemakers and CRT-Ps, this hardware is intended to provide back-up pacing if certain non-recoverable or repeat fault conditions occur. Safety Mode is not intended to be a substitute for chronic pacing therapy. There is a high degree of detectability when a device is operating in Safety Mode. A warning screen is displayed on the programmer upon device interrogation (Figure 1). For those devices monitored via LATITUDE, a red alert will also be issued, indicating the device has entered Safety Mode. If a device is unmonitored for a period of 14 days, it will show up on the 'not monitored' status page on LATITUDE. Whenever a device enters Safety Mode operation, users are instructed to contact Boston Scientific, and Technical Services will advise device replacement.

United States Technical Services

1.800.CARDIAC (227.3422) tech.services@bsci.com

FDA MedWatch

1.800.FDA.1088 (332.1088) www.fda.gov/MedWatch/report.htm

Boston Scientific Advisory: High Battery Impedance May Initiate Safety Mode in INGENIO™ Family DR EL Pacemakers and CRT-Ps




Figure 1. Programmer Warning Screen for Safety Mode

Clinical Impact

Investigation has shown that susceptibility of affected devices is increased when the device reaches approximately three (3) to four (4) years of remaining battery longevity. Based on the available information and subsequent modeling, all dual chamber INGENIO EL pacemakers and CRT-Ps are potentially susceptible to this latent battery condition and subsequent initiation of Safety Mode prior to reaching the Explant battery indicator. However, because implant duration and power usage vary and will impact the rate and degree of battery impedance increase over the lifetime of a device, not all affected devices will manifest in this manner. It is estimated that one third or more of affected devices will experience Safety Mode prior to reaching Explant battery indicator.

No deaths have been reported due to this latent battery condition causing devices to initiate Safety Mode prior to reaching the Explant battery indicator. The potential for life-threatening harm due to prolonged inhibition or loss of pacing over a device's lifetime is estimated to be less than 1 in 15,000; this has not been observed. Although the most common clinical outcome has been early device replacement, Safety Mode parameters may result in unintended clinical impact (e.g., myopotential oversensing-associated pacing inhibition, loss of AV/VV synchrony, phrenic nerve stimulation) for certain patients prior to device replacement. We have observed three instances where patients received external pacing after Safety Mode was initiated. The recommendations below can further reduce this risk.

Recommendations

1. Individual patient evaluation. As noted above, Safety Mode provides back-up pacing under critical circumstances; it is not intended to be a substitute for chronic pacing therapy. When assessing potential risk for a patient if their device initiates Safety Mode prior to the Explant indicator, consider patient-specific physiological factors (which may vary over time), including: adequacy of underlying escape rhythm and/or the need for AV/VV pacing for cardiac synchrony and the potential for pacing inhibition due to myopotential oversensing.
2. Replacement. If a device enters Safety Mode, schedule replacement. Boston Scientific does not recommend general prophylactic replacement for affected devices. However, for individual patients, factors such as those listed above and shared decision-making may support consideration of early device replacement to mitigate unintended clinical impact(s) due to potential entry into Safety Mode prior to the Explant indicator. In these cases, the following guidance should be considered:
 - For EL pacemakers, if early replacement is planned, schedule replacement when the longevity remaining is 4 years (or less, if the device currently indicates fewer than 4 years longevity remaining).
 - For CRT-Ps, if early replacement is planned, schedule replacement when the longevity remaining is 3 years (or less, if the device currently indicates fewer than 3 years longevity remaining).

United States Technical Services

1.800.CARDIAC (227.3422) tech.services@bsci.com

FDA MedWatch

1.800.FDA.1088 (332.1088) www.fda.gov/MedWatch/report.htm

Boston Scientific Advisory: High Battery Impedance May Initiate Safety Mode in INGENIO™ Family DR EL Pacemakers and CRT-Ps

3. Follow-up interval. Perform a system follow-up via remote or in-office interrogation at least every 12 months. For patients who may not require early device replacement, continue with existing follow-up protocols until the longevity reaches One-Year-Remaining and then follow-up every three (3) months thereafter until replacement is indicated (in accordance with the device's instructions for use).
4. Medical records. For each patient with an affected device, append their medical record with this letter to maintain awareness of this topic for the remaining service life of the device.

Adverse events experienced with use of a dual chamber INGENIO EL pacemaker or CRT-P should be reported to Boston Scientific or the FDA's MedWatch Adverse Event Reporting program. Return explanted devices to Boston Scientific. A no cost Return Product kit is available from your local Boston Scientific representative.

Additional Information

Patient safety remains Boston Scientific's highest priority. Although Boston Scientific recognizes the impact of advisory communications on both you and your patients, we are committed to transparent communication with physicians and healthcare professionals to ensure you have timely, relevant information for managing your patients. Up-to-date product performance information, including this topic, and a device lookup tool are available within our Product Performance Resource Center at www.bostonscientific.com/ppr. If you have additional questions regarding this information or would like to report a clinical event, please contact your Boston Scientific representative or Technical Services.

Sincerely,



Alexandra Naughton
Vice President, Quality Assurance

Boston Scientific Advisory: High Battery Impedance May Initiate Safety Mode in INGENIO™ Family DR EL Pacemakers and CRT-Ps

Appendix A: Affected Product Names/Models/Part Numbers

| Product Name | Model | GTIN | Product Name | Model | GTIN |
|----------------|----------------|----------------|----------------|----------------|----------------|
| ADVANTIO DR EL | J064 | 00802526496011 | INGENIO DR EL | K184 | 00802526509698 |
| | | 00802526508868 | | | 00802526509704 |
| | | 00802526508912 | | | 00802526509711 |
| | | 00802526508936 | | | 00802526536809 |
| | | 00802526516429 | | | 00802526536915 |
| | | 00802526525384 | | | 00802526543289 |
| | | 00802526538643 | | | 00802526543685 |
| | | 00802526538667 | 00802526535956 | | |
| | | 00802526539619 | INGENIO DR EL | K187 | 00802526543319 |
| | | 00802526539626 | | | 00802526543715 |
| | | 00802526539640 | | | VITALIO DR EL |
| | | 00802526555619 | VITALIO DR EL | K277 | 00802526528040 |
| | | 00802526566141 | VITALIO DR EL | K284 | 00802526536571 |
| | | 00802526566158 | VITALIO DR EL | K287 | 00802526528071 |
| 00802526496042 | 00802526528170 | | | | |
| 00802526516450 | 00802526543340 | | | | |
| ADVANTIO DR EL | J067 | 00802526518140 | INVIVE CRT-P | V172 | 00802526496479 |
| | | 00802526518157 | | | 00802526536625 |
| | | 00802526518171 | INVIVE CRT-P | V173 | 00802526496486 |
| | | 00802526518195 | | | 00802526536632 |
| | | 00802526525506 | | | 00802526540387 |
| | | 00802526538728 | INVIVE CRT-P | V182 | 00802526498121 |
| | | 00802526538742 | | | 00802526509858 |
| | | 00802526538759 | | | 00802526509865 |
| | | 00802526539817 | | | 00802526536922 |
| | | 00802526539824 | | | 00802526543364 |
| | | 00802526539831 | | | 00802526543777 |
| | | 00802526539855 | INVIVE CRT-P | V183 | 00802526498138 |
| | | 00802526539862 | | | 00802526509872 |
| | | 00802526555640 | | | 00802526509889 |
| | | 00802526566233 | | | 00802526536656 |
| | | 00802526566301 | | | 00802526536939 |
| | | 00802526496073 | | | 00802526543371 |
| | | INGENIO DR EL | J174 | 00802526509339 | INTUA CRT-P |
| 00802526509353 | 00802526536663 | | | | |
| 00802526509360 | 00802526536670 | | | | |
| 00802526509377 | INTUA CRT-P | | | V273 | 00802526536670 |
| 00802526509391 | INLIVEN CRT-P | | | V284 | 00802526543388 |
| 00802526509407 | INLIVEN CRT-P | | | V285 | 00802526536717 |
| 00802526509414 | INVIVE CRT-P | | | W172 | 00802526543395 |
| 00802526516511 | | | | | 00802526496530 |
| 00802526525629 | | | | | 00802526509896 |
| 00802526538810 | | | | | 00802526509919 |
| | | | | | 00802526509926 |

United States Technical Services

1.800.CARDIAC (227.3422) tech.services@bsci.com

FDA MedWatch

1.800.FDA.1088 (332.1088) www.fda.gov/MedWatch/report.htm

Boston Scientific Advisory: High Battery Impedance May Initiate Safety Mode in INGENIO™ Family DR EL Pacemakers and CRT-Ps

Appendix A: Affected Product Names/Models/Part Numbers

| Product Name | Model | GTIN | Product Name | Model | GTIN |
|----------------|----------------|----------------|---------------|-------|----------------|
| INGENIO DR EL | J174 | 00802526538827 | INVIVE CRT-P | W172 | 00802526509933 |
| | | 00802526538834 | | | 00802526509957 |
| | | 00802526538841 | | | 00802526509964 |
| | | 00802526540028 | | | 00802526509988 |
| | | 00802526540035 | | | 00802526526206 |
| | | 00802526540042 | | | 00802526536724 |
| | | 00802526540059 | | | 00802526539220 |
| | | 00802526540066 | | | 00802526539244 |
| | | 00802526540073 | | | 00802526539251 |
| | | 00802526555657 | | | 00802526539268 |
| | | 00802526563102 | | | 00802526566714 |
| | | 00802526566356 | | | 00802526566721 |
| | | 00802526566363 | | | 00802526496547 |
| | | 00802526496103 | | | 00802526510007 |
| INGENIO DR EL | J177 | 00802526516542 | INVIVE CRT-P | W173 | 00802526510021 |
| | | 00802526518423 | | | 00802526510038 |
| | | 00802526518430 | | | 00802526510045 |
| | | 00802526518454 | | | 00802526510069 |
| | | 00802526518478 | | | 00802526510076 |
| | | 00802526518485 | | | 00802526510083 |
| | | 00802526525742 | | | 00802526510090 |
| | | 00802526539022 | | | 00802526526237 |
| | | 00802526539046 | | | 00802526536731 |
| | | 00802526539053 | | | 00802526539275 |
| | | 00802526539060 | | | 00802526539282 |
| | | 00802526540233 | | | 00802526539299 |
| | | 00802526540240 | | | 00802526539305 |
| | | 00802526540257 | | | 00802526539312 |
| | | 00802526540271 | | | 00802526555770 |
| | | 00802526540288 | | | 00802526563140 |
| | | 00802526543425 | | | 00802526566738 |
| | | 00802526555688 | | | 00802526566745 |
| | | 00802526563133 | | | 00802526501593 |
| | | 00802526566516 | | | 00802526501609 |
| 00802526566523 | 00802526501616 | | | | |
| VITALIO DR EL | J274 | 00802526501531 | INTUA CRT-P | W273 | 00802526555787 |
| | | 00802526501548 | | | 00802526566752 |
| | | 00802526501555 | | | 00802526566769 |
| | | 00802526555718 | | | 00802526526350 |
| | | 00802526566592 | | | 00802526531446 |
| VITALIO DR EL | J277 | 00802526566608 | INLIVEN CRT-P | W274 | 00802526531453 |
| | | 00802526516627 | | | 00802526531460 |
| | | 00802526526022 | | | 00802526531484 |

United States Technical Services

1.800.CARDIAC (227.3422) tech.services@bsci.com

FDA MedWatch

1.800.FDA.1088 (332.1088) www.fda.gov/MedWatch/report.htm

Boston Scientific Advisory: High Battery Impedance May Initiate Safety Mode in INGENIO™ Family DR EL Pacemakers and CRT-Ps

Appendix A: Affected Product Names/Models/Part Numbers

| Product Name | Model | GTIN | Product Name | Model | GTIN | | |
|----------------|-------|----------------|----------------|-------|----------------|------|----------------|
| VITALIO DR EL | J277 | 00802526528118 | INLIVEN CRT-P | W274 | 00802526531491 | | |
| | | 00802526539138 | | | 00802526536762 | | |
| | | 00802526539145 | | | 00802526539329 | | |
| | | 00802526539152 | | | 00802526539336 | | |
| | | 00802526539169 | | | 00802526539343 | | |
| | | 00802526566653 | | | 00802526539350 | | |
| | | 00802526566660 | | | 00802526543838 | | |
| ADVANTIO DR EL | K064 | 00802526496233 | | | | | 00802526566776 |
| | | 00802526516719 | | | | | 00802526566783 |
| ADVANTIO DR EL | K084 | 00802526497926 | | | INLIVEN CRT-P | W275 | 00802526526404 |
| | | 00802526509636 | 00802526531514 | | | | |
| | | 00802526509643 | 00802526531521 | | | | |
| | | 00802526536533 | 00802526531538 | | | | |
| | | 00802526536908 | 00802526531552 | | | | |
| | | 00802526543227 | 00802526531569 | | | | |
| | | 00802526543623 | 00802526536779 | | | | |
| ADVANTIO DR EL | K087 | 00802526535925 | | | | | 00802526539374 |
| | | 00802526543258 | | | | | 00802526539381 |
| | | 00802526543654 | | | | | 00802526539398 |
| INGENIO DR EL | K174 | 00802526496295 | | | | | 00802526539404 |
| | | 00802526536786 | | | | | 00802526555794 |
| | | 00802526540363 | | | | | 00802526566790 |
| | | 00802526552809 | | | 00802526566806 | | |

United States Technical Services

1.800.CARDIAC (227.3422) tech.services@bsci.com

FDA MedWatch

1.800.FDA.1088 (332.1088) www.fda.gov/MedWatch/report.htm