
To: Boston Scientific Cardiac Rhythm Management (CRM) Customers
From: CRM Technical Services
Date: June 15, 2009
Subject: Software updates for ZOOM[®] LATITUDE[®] programmers,
COGNIS[®] CRT-Ds, and TELIGEN[®] ICDs

Boston Scientific CRM has initiated a software update for all ZOOM LATITUDE Model 3120 programmers. Upon first interrogation of a COGNIS or TELIGEN device by a programmer with new software installed, the programmer will **automatically** program the Respiratory Sensor to Off, and it can no longer be turned On. Respiratory Sensor data previously stored in device memory can be reviewed on the Respiratory Rate Trending screen, but no new diagnostic data will be added.

Installation of new programmer software (Model 2868, Version 1.05) can be confirmed by viewing the "About" screen from the "Utilities" tab. This software update is being done in response to a product advisory communication dated March 23, 2009.

Further Information

An update to the COGNIS and TELIGEN Instructions for Use ("System Guide") is available at www.bostonscientific.com/ifu. If you have any questions regarding your programmer or Boston Scientific CRM devices, please contact your local CRM representative, United States Technical Services at 1.800.CARDIAC (227.3422) or European Technical Services at +32 2 416 7222.