Prescriptive Information

Refer to the device directions for use for complete instructions on device use.

Caution: Federal Law (USA) restricts this device to sale by or on the order of a physician.

Resuse Warning

For single use only. Do not reuse, reprocess or resterilize. Reuse, reprocessing or resterilization may compromise the structural integrity of the device and/or lead to device failure which, in turn, may result in patient injury, illness or death. Reuse, reprocessing or resterilization may also create a risk of contamination of the device and/or cause patient infection or cross-infection, including, but not limited to, the transmission of infectious disease(s) from one patient to another. Contamination of the device may lead to injury, illness or death of the patient.

Indications For Use/Intended Use

The Resolution 360 Clip in indicated for clip placement within the Gastro-intestinal (GI) tract for the purpose of:

- 1. Endoscopic marking,
- 2. Hemostasis for: Mucosal/sub-mucosal defects <3 cm, Bleeding ulcers, Arteries <2 mm, Polyps <1.5 cm in diameter, Diverticula in the colon, Prophylactic clipping to reduce the risk of delayed bleeding post lesion resection,
- 3. Anchoring to affix jejunal feeding tubes to the wall of the small bowel,
- 4. As a supplementary method, closure of GI tract luminal perforations <20 mm that can be treated conservatively

Contraindications

- · Do not use this device when hemostasis cannot be verified visually with an endoscopic field of view
- · Arteries greater than 2 mm
- Polyps greater than 1.5 cm in diameter
- Mucosal/Submucosal defects greater than 3 cm

WARNINGS

- DO NOT FORCIBLY PULL BACK ON A CLIP THAT IS DEPLOYED AND HAS NOT DETACHED FROM THE COIL. THIS WILL TEAR THE TISSUE AND LIKELY RESULT IN SEVERE BLEEDING OR PERFORATION.
- A wire-cutter should be available on the endoscopy cart and used to cut the coil near the device handle if needed. The endoscope can then be removed leaving the clip and coil intact. The patient may require URGENT SURGERY to separate the clip from the coil without tearing tissue or to manage bleeding resulting from manipulating the imbedded clip.
- Contains nickel, which may cause an allergic reaction in individuals with nickel sensitivity.

- Re-bleeding may occur if the clips detach within 24 hours.
- Although rates of occurrence are low, recurrent bleeding, ineffective clipping or endoscopic complications could result in the need for surgery.
- Clipping hard or severely fibrotic lesions may result in ineffective hemostasis. Additional interventions may be required to control bleeding.
- The Resolution 360 Clip is designed to be compatible with forward viewing endoscopes with working channels equal to or greater than 2.8 mm. Use with a side viewing scope may result in difficulty or inability to deploy, leading to patient injury.

Precaution(s)

- Passage of the Resolution 360™ Clip through a retroflexed or tortuous path, may result in the clip separating from the catheter and potentially kinking or damaging the device.
- Applying tangential pressure to an opened or closed clip may result in the clip separating from the catheter and potentially kinking or damaging the device.
- In a difficult scope position, it may be necessary to straighten the endoscope to facilitate the device passage, then reposition scope for treatment.
- If the device kinks or becomes damaged during insertion or passage, do not use it. Call Boston Scientific Customer Service and return the product.
- It is recommended that the healthcare providers distribute patient implant cards with the name of the clip and date it was placed.

Adverse Events

- · Allergic reaction
- Burn
- Hemorrhage
- Infection
- Inflammation
- Pain
- Perforation
- Surgery
- Tissue Damage